

## Under Review Notification

**Raised By:** Ketan Tailor

**Product #:** RBE350A94-2700-05

**Date:** March 12, 2019

**Product Name:** MAIN ROTOR & TAIL ROTOR RIGGING KIT

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143) (eg. RBEM324U3010101-1)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN / URF Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		DO NOT SHIP	Red Tag/Quarantine Stock	Advise Customers	Hold all Production	Re-Work Stock	PP Under Review (Engineer Signoff Required.)	Put Product Specifications Under Review ("Bluefiles")		
RBE350A94-2700-05	RBE350A94-2700-05 REV. 1	Y	Y	N	Y	Y	Y	N	19-635	Remove items -17, -19, -21
RBE350A94-2700-05-13	RBE350A94-2700-05 REV. 1	Y	Y	N	Y	Y	N	N	19-635	Change foam cutout
RBE350A94-2700-05-15	RBE350A94-2700-05 REV. 1	Y	Y	N	Y	Y	N	N	19-635	Change to pelican case

### Description of Issue:

Items -17, -19, -21 are not required, can be removed from top level.  
 RBE350A94-2706-00 does not fit into bottom foam, need to change to pelican case and update the foam cutout  
 RBE350A94-3701-00 should be RBE350A94-3700-00-01, update BOM and foam cutout

### Distribution:

VP Operations	Director of Engineering	Customer Support Manager	Technical Support
Director of Operations	Chief Engineer	Production Engineers	Product Manager - Solutions Provider
Director Quality Assurance	Engineering Project Managers	Production Planners	Supply Chain Director / Senior Buyer
QC Coordinator	Engineering Clerk	Purchasing Manager	Marketing Eugene